From: Edlund, Carl
To: Meyer, John

Cc: Gray, David; Coleman, Sam; Crossland, Ronnie; Phillips, Pam; Miller, Garyg; Sanchez, Carlos; Walters, Donn;

McCorkhill, Michael; Talton, Anthony

Subject: RE: SJR Flooding Update

Date: Wednesday, June 01, 2016 10:54:15 AM

Thanks ... I think that we should issue a statement when we know more. I appreciate Jackie's offer to be our spokesperson but that is our responsibility

From: Meyer, John

Sent: Wednesday, June 01, 2016 7:47 AM

To: Edlund, Carl <Edlund.Carl@epa.gov>; Phillips, Pam <phillips.pam@epa.gov>

Subject: FW: SJR Flooding Update

Fyi, we are pulling together a response. Will keep David in the loop.

John C Meyer Remedial Branch Chief Superfund Division 214.665.6742



From: Jacquelyn Young [mailto:jeyoung@texanstogether.org]

Sent: Tuesday, May 31, 2016 8:43 PM

To: Miller, Garyg < Miller, Donn < walters.donn@epa.gov>; Gray, David

<gray.david@epa.gov>; Coleman, Sam <<u>Coleman.Sam@epa.gov</u>>; Meyer, John

<<u>Meyer.John@epa.gov</u>>; Sanchez, Carlos <<u>sanchez.carlos@epa.gov</u>>

Cc: Allen, Bob (PCS) < bob.allen@pcs.hctx.net>; Owens, Rock (CAO) < rock.owens@cao.hctx.net>; sjones@galvbay.org; Lisa Gossett < lisa.gossett@sbcglobal.net>; Linda Henry < lhenry@poha.com>; Rodrigo Cantu < RCantu@lonestarlegal.org>; latrice.babin@pcs.hctx.net; Utley, Sarah (CAO) < Sarah.Utley@cao.hctx.net>; Gretchen Knowles < gretchen.knowles@pct2.hctx.net>

Subject: SJR Flooding Update

EPA.

Our residents are extremely concerned about the recent flooding and more rain is on the way. As you know, I sent out emails/photos over the weekend and I am now sending out the most recent photos I have. Please see the photos and information below. As soon as I have a response from the agency, I will let our residents know what steps are being taken to ensure the protection of public health and the environment.

- 1. Recent flooding washed out the Market Street feeder, just south of the Waste Pits along Interstate 10.
- 2. A group of the permanent buoys are currently to the south at Southwest Shipyard.



- 3. Surveillance cameras appear to be displaced.
- 4. The dolphin bumper structure in the San Jacinto River directly east of the Waste Pits. The structure was filled with clean sand and it had a cement top. The structure was reportedly struck by an object traveling down river, releasing the material inside and collapsing the top. 5. Waste Pits on 5/31/16
- 6a,b. Debris shown on Pits

Thank you, Jackie Young





2.









6a.



6b.